



Meter Data Management Agent (MDMA) Subcontractors

1.0. Subcontractors

- 1.1. Subcontractors hired to perform MDMA services are required to meet all SCE and CPUC requirements. SCE requires the MDMA to provide a list of subcontractors employed to perform MDMA services prior to that MDMA becoming qualified. This list shall include:
 - business owner name
 - DBA
 - address
 - mailing address
 - contractor license number
 - length of business ownership
- 1.2. Each MDMA will have on file the training curriculum, safety policies, and performance requirements of the subcontractor. These documents will be available for SCE review upon request.
- 1.3. MDMA's shall provide SCE with a copy of the "Memorandum of Understanding" (or related contractual document) signed by the officers or appropriate personnel of the MDMA and the subcontractor.
- 1.4. MDMA's shall provide SCE with a copy of the operational procedures for back-up MDMA services provided by subcontractors performing MDMA services. This document shall describe the timing of each event that will occur as a back-up to the remote reading process.